

## Learn More About It

### How To Paint With A Brush

1. First fill the brush by dipping it halfway into the paint—don't be bashful and only dip the tips, but don't drown the brush by sinking it up to its ferrule. Tap the brush lightly inside the can or bucket to prevent dripping.
2. Paint in approximately 2-foot square sections at a time. Overlap each section slightly. Brush from unpainted areas into freshly painting ones so that all the sections blend invisibly together.
3. Long, smooth strokes produce a better finish than short, choppy ones. Finish each stroke with a light, lifting motion toward the last wet edge to help prevent brushmarks. Remember, brushing the paint out too thinly can reduce proper hiding qualities. As the brush begins to run out of paint, refill it instead.

Don't press too hard on the brush.

Paint should be applied with the tips of the brush, not the sides.

"Riding the brush" leaves marks in the coating and can bend or break the filament.

